



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program August 11, 2010

Reviewed: 

Mine Name: AMMI	Permit Number: S/019/0035
Operator Name: Absolute Mining and Minerals	Inspection Date: 05/12/2010
Inspector(s): Tom Munson	Time: 10 AM
Other Participants: Dave Skinner(BLM)	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit fee: current

Bond Amount: \$8,200 held by BLM

Purpose of Inspection: To determine what exists on site.

Inspection Summary:

The site was inspected and it was determined that no mining or reclamation has occurred for a long time. All the structures that existed before, were still on site and in various states of disrepair. Most is considered scrap metal that needs to be removed. The site needs to be regraded and seeded as the bond the BLM holds is inadequate to complete reclamation and the operator has not responded to numerous requests for additional bond and updated plans.



Conclusions and Recommendations:

The Division sent a letter to the operator on 6/23/2010 stating that the permit had been withdrawn, ordering reclamation of the site. The Division needs to work with the BLM to reclaim this site, or pursue legal action to relinquish the bond and reclaim the site.

Inspector's Signature



TM:vs

cc: Absolute Mining and Minerals 7752 N 9150 W, Lehi, Ut 84043
marie_mcgann@blm.gov

O:\M019-Grand\S0190035-Ammi\inspections\insp-05112010.doc



One of the flumes



The second flume, tanks and building



Building from reclaimed hillside



Building, tanks and misc. junk



Buried tanks



Close up fo building etc.



Reclaimed area



Buried tanks



Building



Old railroad tanker



Misc. junk



Flume in major disrepair